




US Army Corps of Engineers®

Chicago District
Planning Branch
231 South La Salle Street
Suite 1500
Chicago, Illinois 60604
312-353-6400

Appendix C – Historical Borings Log

Draft Supplemental Environmental Assessment Morgan
Shoal Revetment Reconstruction (45th - 51st)

FILE: C:\pw_working\wtr\cerichard\020439\9\22703-B-100.dwg USER: cerichard DATE: Oct, 03 2023 TIME: 04:22 pm



SHEET NOTES

- 2022 BORINGS WERE COMPLETED BY WANG ENGINEERING INC. IN 2022 AND HISTORICAL BORINGS ARE PERFORMED BY OTHERS IN THE 1990s AND EARLY 2000s.
- SEE GEOTECHNICAL PROFILES OF UPPER PLAN AND LOWER PLAN ON SHEETS B-101 AND B-102, RESPECTIVELY.
- VANE SHEAR AND PRESSURE METER TEST WERE COMPLETED ALONG WITH THE 2022 BORING SCHEDULE.

LEGEND

- GEOTECHNICAL PROFILE B6 TO LS-03
- GEOTECHNICAL PROFILE H22-01 TO H22-05
- H22-02 APPROXIMATE 2022 SOIL BORING LOCATION
- H22-01 VST-PMT APPROXIMATE 2022 SOIL BORING LOCATION (FOR VANE SHEAR AND PRESSURE METER TESTS)
- MS-01 APPROXIMATE 2004 SOIL BORING LOCATION (EXISTING)
- CB4-4-94 APPROXIMATE LOCATION OF PREVIOUS HISTORICAL BORINGS

NOT FOR CONSTRUCTION



CHICAGO SHORELINE PROTECTION PROJECT
MORGAN SHOAL REVETMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60663
CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record:
SMITHGROUP
ADDRESS: 35 EAST WACKER SUITE 800
CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770
WEB: www.smithgroup.com


- Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record
- Infrastructure Engineering, Inc.
Chicago, IL
Civil Engineers of Record
- Latent Design Corporation
Chicago, IL
Architects
- Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant
- Living Habitats, LLC
Chicago, IL
Ecological Consultant
- American Surveying & Engineering
Chicago, IL
Surveying Consultant
- CCJM Engineers
Chicago, IL
MEP Consultant
- Thornton Tomasetti
Chicago, IL
Structural Consultant

Issuance		
Mark	Description	Date
1	Schematic Design	05/2022
2	60% Detailed Design	01/2023
3	90% Final Engineering	10/2023

PBC Project Name: Chicago Shoreline Protection Project
PBC Contract No.: 22703
Project No.: 13678

Title: 2022 AND PREVIOUS HISTORICAL BORINGS

Sheet
B-100



SHEET NOTES


1. THIS GEOTECHNICAL PROFILE ALONG THE ALIGNMENT WAS PREPARED BY WANG ENGINEERING INC (WEI). ALL INFORMATION AND LITHOLOGICAL INTERPRETATIONS ARE FOR INFORMATION ONLY. FOR GEOTECHNICAL INFORMATION REFER TO GEOTECHNICAL DATA REPORT PREPARED BY (WEI) AND INCLUDED IN THE SPECIFICATIONS.
2. THE BOUNDARY BETWEEN THE SOIL LAYERS AND LITHOLOGIES SHOWN ON THIS DRAWING AND PRESENTED IN THE WANG GEOTECHNICAL REPORT ARE BOTH BASED ON INTERPRETATIONS AND APPROXIMATIONS AND COULD VARY IN THE FIELD, ESPECIALLY BETWEEN THE BOREHOLE LOGS.

NOT FOR
CONSTRUCTION

SOUTH

2022 BORINGS


NORTH




LITHOLOGY GRAPHICS




USCS Poorly-graded Sandy Gravel




USCS Poorly-graded Sand




USCS Low Plasticity Sandy Clay




Topsoil




USCS Low Plasticity Silty Clay




Weathered bedrock




USCS Silty Sand



USCS Well-graded Sand



USCS Poorly-graded Gravelly Sand



CHICAGO SHORELINE PROTECTION PROJECT
MORGAN SHOAL REVETMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60653
CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record:
SMITHGROUP
ADDRESS: 35 EAST WACKER SUITE 800
CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770
WEB: www.smithgroup.com

Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record

Infrastructure Engineering, Inc.
Chicago, IL
Civil Engineers of Record

Latent Design Corporation
Chicago, IL
Architects

Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant

Living Habitats, LLC
Chicago, IL
Ecological Consultant

American Surveying & Engineering
Chicago, IL
Surveying Consultant

CCJM Engineers
Chicago, IL
MEP Consultant

Thornton Tomasetti
Chicago, IL
Structural Consultant


Mark	Description	Date
1	Schematic Design	05/2022
2	60% Detailed Design	01/2023
3	90% Final Engineering	10/2023

PBC Project Name: Chicago Shoreline Protection Project
PBC Contract No.: 22703
Project No.: 13678

Title
**GEOTECHNICAL
PROFILE
SHEET 1 OF 2**

Sheet
B-101

FILE: C:\pw_working\wtr\cerichard\2024\3919\22703-B-102.dwg USER: cerichard DATE: Oct, 03 2023 TIME: 04:22 pm



SHEET NOTES

1. N REPRESENTS THE STANDARD PENETRATION BLOW COUNTS AND QU (TSF) REPRESENTS UNCONFINED COMPRESSION STRENGTH OF THE SOIL MATERIAL LAYERS.
2. THIS BOREHOLE LOG PROFILE IS FOR INFORMATION ONLY. IN CASE OF DISCREPANCY BETWEEN THIS PROFILE INFORMATION AND BOREHOLE LOG INFORMATION FOR LITHOLOGY, N AND QU VALUES, THE INFORMATION IN THE BOREHOLE LOGS SHALL GOVERN.

LEGEND

FILL/ RUBBLE	FILL MATERIAL
SP/SM & GW/GM	SAND AND GRAVEL LOOSE TO MEDIUM DENSE, FINE TO MEDIUM GRAINED
CL & CL/ML	SOFT TO MEDIUM TO STIFF CLAY
CL	STIFF SILTY CLAY
CL/ML & SC/SM	HARD SILTY CLAY - CLAYEY SAND /GRAVEL - HARDPAN
ROCK	BEDROCK/ BOULDER/ REFUSAL

NOT FOR CONSTRUCTION



CHICAGO SHORELINE PROTECTION PROJECT

MORGAN SHOAL REVETMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60653

CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record:

SMITHGROUP

ADDRESS: 35 EAST WACKER SUITE 800
CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770
WEB: www.smithgroup.com

Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record

Infrastructure Engineering, Inc.
Chicago, IL
Civil Engineers of Record

Latent Design Corporation
Chicago, IL
Architects

Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant

Living Habitats, LLC
Chicago, IL
Ecological Consultant

American Surveying & Engineering
Chicago, IL
Surveying Consultant

CCJM Engineers
Chicago, IL
MEP Consultant

Thornton Tomasetti
Chicago, IL
Structural Consultant

Mark	Description	Date
1	Schematic Design	05/2022
2	60% Detailed Design	01/2023
3	90% Final Engineering	10/2023

PBC Project Name: Chicago Shoreline Protection Project
PBC Contract No.: 22703
Project No.: 13678
Title
GEOTECHNICAL PROFILE
SHEET 2 OF 2
Sheet

B-102

BORING LOG H22-01

Relative Drilling Resistance		
RDR	Term	Criterion
1	Very Easy	No chatter, very little resistance, very fast and steady drill advance
2	Easy	No chatter, some resistance, fast and steady drill advance rate
3	Moderate	Some chatter, firm drill resistance, moderate advance
4	Hard	Frequent chatter, variable drill resistance, slow advance rate
5	Very Hard	Constant chatter, variable and very slow drill advance, nearly refusal

Coarse Gradation (mm) (ASTM D2488)		
Gravel	4.75 to 75	
Cobbles	75 to 300	
Boulders	> 300	


Proportional Terms (%) (ASTM D2488)		
Trace	< 5	
Few	5 to 10	
Little	15 to 25	
Some	30 to 45	
Mostly	50 to 100	

Relative Density of Non-Cohesive Soils (ASTM D1586)		
No. of Blows/ft	Relative Density	
0 - 4	Very Loose	
4 - 10	Loose	
10 - 30	Medium Dense	
30 - 50	Dense	
> 50	Very Dense	

Consistency of Cohesive Soils (ASTM D1586)		
Qu (tsf)	Consistency	
< 0.25	Very Soft	
0.25 - 0.50	Soft	
0.50 - 1.00	Medium Stiff	
1.00 - 2.00	Stiff	
2.00 - 4.00	Very Stiff	
> 4.00	Hard	

Soil Moisture Conditions	
Term	Appearance and Feel
Dry	Soil sample looks and feels powdery or dusty; no indication of moisture. Free-running granular soils. Cohesive soils cannot be molded easily without adding water. Granular soil may not flow very easily.
Damp	Soil is near the optimum moisture content. Cohesive soils are near the plastic limit. Soil changes color slightly when exposed to air for a short period.
Moist	One may feel a high degree of moisture, yet no free water is visible. Water may become visible if the sample is squeezed. Cohesive soil appears weak and sticks to and/or stains hands. Granular soils tend to cohere.
Wet	Applied to granular soils that have free surface water; water drains freely from the sample.
Saturated	

Sample Type Symbols



Geotechnical • Construction • Environmental
Quality Engineering Services Since 1982

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-01
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 11.80 ft
North: 1873791.73 ft
East: 1187869.21 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
Medium dense, brown, poorly-graded GRAVEL with sand (CL)s, trace brick fragments, damp	11	4	1	11	0.80	22
Hard, gray LEAN CLAY with sand (CL)s, trace little gravel; damp	12	5	2	12	8.61	15
Very loose to loose, gray, poorly-graded, fine SAND (SP); moist to saturated	13	20	3	13	10.25	14
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	14	21	4	14	50.0	
Very soft to medium stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	15	0.16	5	15		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	16	0.74	6	16		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	17	0.82	7	17		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	18	0.41	8	18		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	19	0.23	9	19		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	20	1.23	10	20		

GENERAL NOTES	
Begin Drilling	11-01-2022
Complete Drilling	11-01-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 10 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	8.50 ft
At Completion of Drilling	mud in borehole
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-01VST/PMT
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 11.80 ft
North: 1873787.09 ft
East: 1187873.70 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
Blind drill to 26 feet	11	4	1	11	0.80	22
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel	12	5	2	12	8.61	15
Gray LEAN CLAY with sand (CL)s, trace gravel	13	20	3	13	10.25	14
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel	14	21	4	14	50.0	
Very soft to medium stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	15	0.16	5	15		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	16	0.74	6	16		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	17	0.82	7	17		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	18	0.41	8	18		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	19	0.23	9	19		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	20	1.23	10	20		

GENERAL NOTES	
Begin Drilling	11-03-2022
Complete Drilling	11-03-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 10 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	NA
At Completion of Drilling	NA
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-02
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 11.10 ft
North: 1873234.75 ft
East: 1188153.29 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
12-inch thick, black SILTY SAND (SM)	11	4	1	11	8.61	13
Loose to medium dense, black and gray, poorly-graded GRAVEL with sand (GP)s, trace cobbles; damp	12	20	2	12	10.25	9
Very dense, gray DOLOSTONE FRAGMENTS	13	29	3	13	4.50	10
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp to saturated	14	30	4	14	50.0	
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	15	0.16	5	15		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	16	0.74	6	16		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	17	0.82	7	17		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	18	0.41	8	18		
Very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	19	0.23	9	19		
Medium stiff to stiff, gray LEAN CLAY with sand (CL)s, trace gravel; damp	20	1.23	10	20		

GENERAL NOTES	
Begin Drilling	11-01-2022
Complete Drilling	11-01-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 10 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	9.00 ft
At Completion of Drilling	mud in borehole
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-03
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 11.60 ft
North: 1872874.69 ft
East: 1188473.16 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
4-inch thick, black LEAN CLAY (CL)	11	4	1	11	4.00	15
Loose, gray, silty SAND (SM), few lean clay laminations; moist	12	9	2	12	8.20	15
Hard, gray LEAN CLAY with sand (CL)s; damp	13	11	3	13	8.20	15
Loose to medium dense, brown, poorly-graded, fine SAND (SP); trace gravel; damp to saturated	14	12	4	14	9.02	13
Hard, gray SILTY CLAY (CL-ML), trace gravel; damp	15	19	5	15	5.33	11
Soft (0.25P), gray LEAN CLAY with sand (CL)s, trace gravel	16	21	6	16	9.02	11

GENERAL NOTES	
Begin Drilling	10-31-2022
Complete Drilling	10-31-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 10 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	8.00 ft
At Completion of Drilling	mud in borehole
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-04
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 11.50 ft
North: 1872274.04 ft
East: 1188125.35 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
Medium dense, brown, poorly-graded GRAVEL with sand (GP)s, trace brick fragments, damp	11	4	1	11	2.87	17
Loose, black, well-graded SAND (SW), trace gravel and brick fragments; damp	12	9	2	12	2.13	20
Brown, poorly-graded, fine SAND (SP); damp	13	7	3	13	2.87	24
Hard, gray SILTY CLAY (CL-ML), trace gravel; damp	14	7	4	14	5.90	14
Very loose to loose, black, poorly-graded, medium SAND with gravel (SP)g, trace brick fragments, saturated	15	13	5	15	9.43	14
Very loose to loose, gray, poorly-graded, fine SAND (SP); trace gravel; saturated	16	8	6	16	6.97	14

GENERAL NOTES	
Begin Drilling	11-02-2022
Complete Drilling	11-02-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 16 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	8.00 ft
At Completion of Drilling	mud in borehole
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-05
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 10.00 ft
North: 1872024.75 ft
East: 1188469.10 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
Loose to medium dense, black and brown, poorly-graded, fine to medium SAND with gravel (SP)g, trace brick fragments; damp to saturated	11	4	1	11	1.31	20
Stiff to very stiff, gray LEAN CLAY with sand (CL)s, trace gravel; moist	12	4	2	12	1.38	20
Very loose to medium dense, brown to gray, poorly-graded, fine SAND (SP); trace gravel; saturated	13	8	3	13	2.05	21
Hard, gray LEAN CLAY with sand (CL)s, trace gravel; damp	14	9	4	14	6.97	15
Very loose to medium dense, brown to gray, poorly-graded, fine SAND (SP); trace gravel; saturated	15	7	5	15	8.77	14
Very loose to medium dense, brown to gray, poorly-graded, fine SAND (SP); trace gravel; saturated	16	10	6	16	10.25	14

GENERAL NOTES	
Begin Drilling	10-31-2022
Complete Drilling	10-31-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 15 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	8.00 ft
At Completion of Drilling	mud in borehole
Time After Drilling	NA
Depth to Water	NA

Wang Engineering
wangeng@wangeng.com
1145 N Main Street
Lombard, IL 60148
Telephone: 630 953-9928
Fax: 630 953-9938

BORING LOG H22-05VST/PMT
WEI Job No.: KE225171
Client: **SmithGroup**
Project: **Morgan Shoal Revetment**
Location: **Chicago, IL**

Datum: LWD
Elevation: 10.00 ft
North: 1872027.31 ft
East: 1188469.42 ft
Station: NA
Offset: NA

SOIL AND ROCK DESCRIPTION		Depth (ft)	Sample No.	SPT Value (blows/ft)	Qu (tsf)	Moisture Content (%)
Blind drill to 26 feet	11	4	1	11	1.50	
Gray LEAN CLAY with sand (CL)s, trace gravel	12	4	2	12	1.50	
Blind drill to 40 feet	13	4	3	13	1.50	

GENERAL NOTES	
Begin Drilling	11-02-2022
Complete Drilling	11-02-2022
Drilling Contractor	Wang Testing Services, Inc.
Driller	RR&AG
Logger	M. Rojo
Checked by	J. Bensen
Drilling Method	2.25" ID HSA to 15 ft, mud rotary thereafter, boring
backfilled upon completion	

WATER LEVEL DATA	
While Drilling	NA
At Completion of Drilling	NA
Time After Drilling	NA
Depth to Water	NA

NOT FOR CONSTRUCTION



CHICAGO SHORELINE PROTECTION PROJECT
MORGAN SHOAL REVELMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60653
CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record:
SMITHGROUP
ADDRESS: 35 EAST WACKER SUITE 800
CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770
WEB: www.smithgroup.com

Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record

Infrastructure Engineering, Inc.
Chicago, IL
Civil Engineers of Record

Latent Design Corporation
Chicago, IL
Architects

Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant

Living Habitats, LLC
Chicago, IL
Ecological Consultant

American Surveying & Engineering
Chicago, IL
Surveying Consultant






CCJM Engineers
Chicago, IL
MEP Consultant






Thornton Tomasetti
Chicago, IL
Structural Consultant

Mark	Description	Date
1	Schematic Design	05/2022
2	60% Detailed Design	01/2023
3	90% Final Engineering	10/2023

PBC Project Name: Chicago Shoreline Protection Project
PBC Contract No.: 22703
Project No.: 13578
Title: 2022 BORING LOGS

Sheet
B-103





<									
--	--	--	--	--	--	--	--	--	--

SOIL BORING LOG										Boring: LS-03			
MWH		Project: Chicago Shoreline Protection Project								Sheet No.: 4 of 4			
Feature: 45th Street to 51st Street		Feature: 45th Street to 51st Street								Job No.: 4070029			
Date Started: 5/10/04		Date Completed: 5/10/04		Logged By: J. Jobst		Checked By: J. Jobst		Total Depth (ft): 74.0					
Drilling Contr.: Stryker Drilling		Depth to Water (ft): 6.3 WD		Northing: 1871934		Easting: 1189567		Ground Elev.: 9.7					
Drill Rig: Diedrich D-50		Hammer: Automatic											
Depth (ft)	Elevation (ft)	Sample No.	Sample Type	Sample Interval	Blow# in.	SPT N (blf)	Qp (tsf)	Wc (%)	PD (c-ppm)	Soil Descriptions	Profile	Well Schematic	Notes and Observations
60	-50.3									Continuation:			
61	-51.3												
62	-52.3		HSA										
63	-53.3												
64	-54.3												
65	-55.3	20	SPT	19	36	68							
66	-56.3												
67	-57.3		HSA										
68	-58.3												
69	-59.3	21	SPT	34	72/6"					No recovery. Pushed cobble.			Potential cobbles and boulders.
70	-60.3												
71	-61.3		HSA										
72	-62.3												
73	-63.3												
74	-64.3	22	SPT	75/6"						Dolomite bedrock in tip of spoon.			Spoon bouncing.
75	-65.3									End of boring at 74.0'. Borehole backfilled with cuttings and bentonite chips and abandoned upon completion.			Bedrock
76	-66.3												
77	-67.3												
78	-68.3												
79	-69.3												
80	-70.3												

 MWH MOORE SWARTZ KURTZ WATSON HARRIS		SOIL BORING LOG					Boring: MS-01A						
		Project: Chicago Shoreline Protection Project					Sheet No.: 1 of 2						
		Feature: 45th Street to 51st Street					Job No.: 4070029						
Date Started: 4/26/04		Date Completed: 4/26/04		Logged By: J. Jobst		Checked By:							
Total Depth (ft): 38.0'		Depth to Water (ft): n/a		Nothing:		1874705							
Drilling Contr.: Patrick Drilling		Driller: J. Copak		Easting:		1187974							
Drill Rig: CME-75 ATV		Hammer: Automatic		Ground Elev.:		0.0							
Depth (ft)	Elevation (ft)	Sample No.	Sample Type	Sample Interval	Blow# in.	SPT N (blf)	Qp (tsf)	Wc (%)	PD (c-ppm)	Soil Descriptions	Profile	Well Schematic	Notes and Observations
0	0									Lake Michigan			
1	-1												
2	-2												
3	-3												
4	-4												
5	-5												
6	-6												
7	-7												
8	-8												
9	-9												
10	-10												
11	-11												
12	-12												
13	-13												
14	-14												
15	-15												
16	-16												
17	-17												
18	-18												
19	-19												
20	-20									Lake bottom at 20.0'			Move to location estimated 200' north of Boring MS-01.
													Lake Michigan

 MWH MWH CONSULTING SERVICES CORPORATION		Project: Chicago Shoreline Protection Project Feature: 45th Street to 51st Street				Boring: MS-01A Sheet No.: 2 of 2 Job No.: 4070029							
Date Started: 4/26/04		Date Completed: 4/26/04		Logged By: J. Jobst		Checked By:							
Total Depth (ft): 38.0'		Depth to Water (ft): n/a		Northing: 1874705		Easting: 1187974							
Drilling Contr.: Patrick Drilling		Driller: J. Copak		Ground Elev.: 0.0									
Drill Rig: CME-75 ATV		Hammer: Automatic											
Depth (ft)	Elevation (ft)	Sample No.	Sample Type	Sample Interval	Blow# in.	SPT N (blf)	Qp (tsf)	Wc (%)	PD (c-ppm)	Soil Descriptions	Profile	Well Schematic	Notes and Observations
20	-20									Continuation:			
21	-21									Blind drill down to top of rock.			
22	-22												
23	-23												
24	-24												
25	-25												
26	-26												
27	-27												Soil Overburden
28	-28												
29	-29												
30	-30												
31	-31												
32	-32												
33	-33									Auger refusal at 33'0".			
34	-34									DOLOMITE: Light greenish-gray, fine grained, very thinly bedded with green shaley partings (hard/firm), fresh, moderately hard, moderately dense, with few vugs/pitting. Weak bedding planes evident from core breakage along shaley partings.			Rock cored with NX-size and core barrel.
35	-35									RUN 1: 33'-38"			
36	-36									REC: 52'/60" (87%)			Bedrock
37	-37									RQD: 37'/60" (62%)			
38	-38												
39	-39									End of boring. Borehole abandoned upon completion.			
40	-40												

SOIL BORING LOG										Boring: MS-01B			
MWH		Project: Chicago Shoreline Protection Project								Sheet No.: 1 of 3			
MODT/GEOMETRY/HATSON/HARZA		Feature: 45th Street to 51st Street								Job No.: 4070029			
Date Started: 4/26/04		Date Completed: 4/26/04		Logged By: J. Jobst		Checked By:		Total Depth (ft): 54.0'					
Total Depth (ft): 54.0'		Depth to Water (ft): n/a		Northing: 1875097		Easting: 1187611		Ground Elev.: -1.0					
Drilling Contr.: Patrick Drilling		Driller: J. Copak		Drill Rig: CME-75 ATV		Hammer: Automatic							
Depth (ft)	Elevation (ft)	Sample No.	Sample Type	Sample Interval (Feet)	Blow# in.	SPT N (blf)	Qp (tsf)	Wc (%)	PIB (c-ppm)	Soil Descriptions	Profile	Well Schematic	Notes and Observations
0	-1									Lake Michigan			
1	-2												
2	-3												
3	-4												
4	-5												
5	-6												
6	-7												
7	-8												
8	-9												
9	-10												
10	-11												
11	-12												
12	-13												
13	-14												
14	-15												
15	-16												
16	-17												
17	-18												
18	-19									Lake bottom at 18.0'.			
19	-20									Blind drill down to top of rock.			
20	-21												

 MWH WATSON WATSON WATSON	SOIL BORING LOG				Boring: MS-01B								
	Project: Chicago Shoreline Protection Project				Sheet No.: 2 of 3								
Feature: 49th Street to 51st Street				Job No.: 4070029									
Date Started: 4/26/04		Date Completed: 4/26/04		Logged By: J. Jobst									
Total Depth (ft): 54.0'		Depth to Water (ft): n/a		Checked By:									
Drilling Contr.: Patrick Drilling		Driller: J. Copak		1875097									
Drill Rig: CME-75 ATV		Hammer: Automatic		Easting: 1187611									
				Ground Elev.: -1.0									
Depth (ft)	Elevation (ft)	Sample No.	Sample Type	Sample Interval	Borehole In.	SPT N (spt)	Op (sft)	Wc (%)	PIU (- ppm)	Soil Descriptions	Profile	Well Schematic	Notes and Observations
20 -21										Continuation:			
21 -22													
22 -23													
23 -24													
24 -25													
25 -26													
26 -27													
27 -28													
28 -29													
29 -30													
30 -31													
31 -32													
32 -33													
33 -34													
34 -35													Soil Overburden
35 -36													
36 -37													
37 -38													
38 -39													
39 -40													
40 -41													

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-03
Sheet No.: 1 of 1
Job No.: 4070029
Date Started: 4/20/04
Date Completed: 4/20/04
Logged By: J. Jobst
Checked By: 1873192
Total Depth (ft): 12.2
Depth to Water (ft): n/a
North: 1873192
Drilling Contr.: Patrick Drilling
Driller: J. Copak
Easting: 1189611
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.0
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 11.7'.
Weathered dolomitic limestone, light olive gray, fine grained, no apparent bedding, hard, moderately dense to dense, vuggy with some pitting and solutioning.
End of boring at 12.2'. Borehole abandoned upon completion.
Driller attempts to core but barge is drifting slightly due to wave action and no overburden material at hole location. Driller retrieves 0.5' of core before forced to end run. RUN 1: 11.7'-12.2'. REC: 8" (100%) RQD: N/A

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-03A
Sheet No.: 1 of 1
Job No.: 4070029
Date Started: 4/20/04
Date Completed: 4/20/04
Logged By: J. Jobst
Checked By: 1873191
Total Depth (ft): 17.0
Depth to Water (ft): n/a
North: 1873191
Drilling Contr.: Patrick Drilling
Driller: J. Copak
Easting: 1189594
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.0
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 11.0'.
DOLomite: Light olive gray, fine grained, thinly bedded, slightly weathered in locations to fresh, hard, dense, with fine vugs, some solutioning and pitting. Some bedding planes have soft to medium firm gray clayey infilling.
RUN 1: 11.0'-17.0'. REC: 74" (72%) (100%) RQD: 34" (74") (48%)
Bedrock
End of Boring at 17.0'. Borehole abandoned upon completion.

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 1 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 2 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 3 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

SOIL BORING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 4 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

DRILLING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 5 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

DRILLING LOG
Project: Chicago Shoreline Protection Project
Feature: 45th Street to 51st Street
Boring: MS-04
Sheet No.: 6 of 4
Job No.: 4070029
Date Started: 4/21/04
Date Completed: 4/21/04
Logged By: J. Jobst
Checked By: 1872157
Total Depth (ft): 62.0
Depth to Water (ft): n/a
North: 1872157
Drilling Contr.: Patrick Drilling
Driller: T. Zwolinski
Easting: 1189888
Drill Rig: CME-75 ATV
Hammer: Automatic
Ground Elev.: 0.1
Soil Descriptions: Lake Michigan
Notes and Observations: Lake Michigan
Lake bottom at 16.0'.
Medium (firm) gray silty CLAY, medium plastic, moist (CL).
Auger down to 17.0' with 3.25" ID HSA with center plug. Torvane = 1.75 tsf. Auger drift giving driller problems.
Silty Clay
Torvane = 1.75 tsf

NOT FOR CONSTRUCTION



CHICAGO SHORELINE PROTECTION PROJECT
MORGAN SHOAL REVETMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60663
CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record: SMITHGROUP
ADDRESS: 35 EAST WACKER SUITE 800 CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770 WEB: www.smithgroup.com

Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record

Latent Design Corporation
Chicago, IL
Architects

Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant

Living Habitats, LLC
Chicago, IL
Ecological Consultant

American Surveying & Engineering
Chicago, IL
Surveying Consultant

CCJM Engineers
Chicago, IL
MEP Consultant

Thornton Tomasetti
Chicago, IL
Structural Consultant

Historical Boring Logs SHEET 4 OF 5
B-107

Hole No. CB4-2897	
DRILLING LOG	
DIVISION North Central	
PROJECT Chicago Shoreline Reach 4 - 5235.L0	
1. PROJECT	
2. LOCATION (Coordinates or Station)	
3. DRILLING AGENCY	
4. HOLE NO. (As shown on drawing site and file number)	
5. NAME OF DRILLER	
6. ELEVATION GROUND WATER	
7. THICKNESS OF OVERBURDEN	
8. DEPTH DRILLED INTO ROCK	
9. TOTAL DEPTH OF HOLE	
10. ELEVATION TOP OF HOLE	
11. ELEVATION TOP OF HOLE	
12. ELEVATION TOP OF HOLE	
13. ELEVATION TOP OF HOLE	
14. ELEVATION TOP OF HOLE	
15. ELEVATION TOP OF HOLE	
16. ELEVATION TOP OF HOLE	
17. ELEVATION TOP OF HOLE	
18. ELEVATION TOP OF HOLE	
19. ELEVATION TOP OF HOLE	
20. ELEVATION TOP OF HOLE	
21. ELEVATION TOP OF HOLE	
22. ELEVATION TOP OF HOLE	
23. ELEVATION TOP OF HOLE	
24. ELEVATION TOP OF HOLE	
25. ELEVATION TOP OF HOLE	
26. ELEVATION TOP OF HOLE	
27. ELEVATION TOP OF HOLE	
28. ELEVATION TOP OF HOLE	
29. ELEVATION TOP OF HOLE	
30. ELEVATION TOP OF HOLE	
31. ELEVATION TOP OF HOLE	
32. ELEVATION TOP OF HOLE	
33. ELEVATION TOP OF HOLE	
34. ELEVATION TOP OF HOLE	
35. ELEVATION TOP OF HOLE	
36. ELEVATION TOP OF HOLE	
37. ELEVATION TOP OF HOLE	
38. ELEVATION TOP OF HOLE	
39. ELEVATION TOP OF HOLE	
40. ELEVATION TOP OF HOLE	
41. ELEVATION TOP OF HOLE	
42. ELEVATION TOP OF HOLE	
43. ELEVATION TOP OF HOLE	
44. ELEVATION TOP OF HOLE	
45. ELEVATION TOP OF HOLE	
46. ELEVATION TOP OF HOLE	
47. ELEVATION TOP OF HOLE	
48. ELEVATION TOP OF HOLE	
49. ELEVATION TOP OF HOLE	
50. ELEVATION TOP OF HOLE	
51. ELEVATION TOP OF HOLE	
52. ELEVATION TOP OF HOLE	
53. ELEVATION TOP OF HOLE	
54. ELEVATION TOP OF HOLE	
55. ELEVATION TOP OF HOLE	
56. ELEVATION TOP OF HOLE	
57. ELEVATION TOP OF HOLE	
58. ELEVATION TOP OF HOLE	
59. ELEVATION TOP OF HOLE	
60. ELEVATION TOP OF HOLE	
61. ELEVATION TOP OF HOLE	
62. ELEVATION TOP OF HOLE	
63. ELEVATION TOP OF HOLE	
64. ELEVATION TOP OF HOLE	
65. ELEVATION TOP OF HOLE	
66. ELEVATION TOP OF HOLE	
67. ELEVATION TOP OF HOLE	
68. ELEVATION TOP OF HOLE	
69. ELEVATION TOP OF HOLE	
70. ELEVATION TOP OF HOLE	
71. ELEVATION TOP OF HOLE	
72. ELEVATION TOP OF HOLE	
73. ELEVATION TOP OF HOLE	
74. ELEVATION TOP OF HOLE	
75. ELEVATION TOP OF HOLE	
76. ELEVATION TOP OF HOLE	
77. ELEVATION TOP OF HOLE	
78. ELEVATION TOP OF HOLE	
79. ELEVATION TOP OF HOLE	
80. ELEVATION TOP OF HOLE	
81. ELEVATION TOP OF HOLE	
82. ELEVATION TOP OF HOLE	
83. ELEVATION TOP OF HOLE	
84. ELEVATION TOP OF HOLE	
85. ELEVATION TOP OF HOLE	
86. ELEVATION TOP OF HOLE	
87. ELEVATION TOP OF HOLE	
88. ELEVATION TOP OF HOLE	
89. ELEVATION TOP OF HOLE	
90. ELEVATION TOP OF HOLE	
91. ELEVATION TOP OF HOLE	
92. ELEVATION TOP OF HOLE	
93. ELEVATION TOP OF HOLE	
94. ELEVATION TOP OF HOLE	
95. ELEVATION TOP OF HOLE	
96. ELEVATION TOP OF HOLE	
97. ELEVATION TOP OF HOLE	
98. ELEVATION TOP OF HOLE	
99. ELEVATION TOP OF HOLE	
100. ELEVATION TOP OF HOLE	

Hole No. CB4-2897	
DRILLING LOG	
DIVISION North Central	
PROJECT Chicago Shoreline Reach 4 - 5235.L0	
1. PROJECT	
2. LOCATION (Coordinates or Station)	
3. DRILLING AGENCY	
4. HOLE NO. (As shown on drawing site and file number)	
5. NAME OF DRILLER	
6. ELEVATION GROUND WATER	
7. THICKNESS OF OVERBURDEN	
8. DEPTH DRILLED INTO ROCK	
9. TOTAL DEPTH OF HOLE	
10. ELEVATION TOP OF HOLE	
11. ELEVATION TOP OF HOLE	
12. ELEVATION TOP OF HOLE	
13. ELEVATION TOP OF HOLE	
14. ELEVATION TOP OF HOLE	
15. ELEVATION TOP OF HOLE	
16. ELEVATION TOP OF HOLE	
17. ELEVATION TOP OF HOLE	
18. ELEVATION TOP OF HOLE	
19. ELEVATION TOP OF HOLE	
20. ELEVATION TOP OF HOLE	
21. ELEVATION TOP OF HOLE	
22. ELEVATION TOP OF HOLE	
23. ELEVATION TOP OF HOLE	
24. ELEVATION TOP OF HOLE	
25. ELEVATION TOP OF HOLE	
26. ELEVATION TOP OF HOLE	
27. ELEVATION TOP OF HOLE	
28. ELEVATION TOP OF HOLE	
29. ELEVATION TOP OF HOLE	
30. ELEVATION TOP OF HOLE	
31. ELEVATION TOP OF HOLE	
32. ELEVATION TOP OF HOLE	
33. ELEVATION TOP OF HOLE	
34. ELEVATION TOP OF HOLE	
35. ELEVATION TOP OF HOLE	
36. ELEVATION TOP OF HOLE	
37. ELEVATION TOP OF HOLE	
38. ELEVATION TOP OF HOLE	
39. ELEVATION TOP OF HOLE	
40. ELEVATION TOP OF HOLE	
41. ELEVATION TOP OF HOLE	
42. ELEVATION TOP OF HOLE	
43. ELEVATION TOP OF HOLE	
44. ELEVATION TOP OF HOLE	
45. ELEVATION TOP OF HOLE	
46. ELEVATION TOP OF HOLE	
47. ELEVATION TOP OF HOLE	
48. ELEVATION TOP OF HOLE	
49. ELEVATION TOP OF HOLE	
50. ELEVATION TOP OF HOLE	
51. ELEVATION TOP OF HOLE	
52. ELEVATION TOP OF HOLE	
53. ELEVATION TOP OF HOLE	
54. ELEVATION TOP OF HOLE	
55. ELEVATION TOP OF HOLE	
56. ELEVATION TOP OF HOLE	
57. ELEVATION TOP OF HOLE	
58. ELEVATION TOP OF HOLE	
59. ELEVATION TOP OF HOLE	
60. ELEVATION TOP OF HOLE	
61. ELEVATION TOP OF HOLE	
62. ELEVATION TOP OF HOLE	
63. ELEVATION TOP OF HOLE	
64. ELEVATION TOP OF HOLE	
65. ELEVATION TOP OF HOLE	
66. ELEVATION TOP OF HOLE	
67. ELEVATION TOP OF HOLE	
68. ELEVATION TOP OF HOLE	
69. ELEVATION TOP OF HOLE	
70. ELEVATION TOP OF HOLE	
71. ELEVATION TOP OF HOLE	
72. ELEVATION TOP OF HOLE	
73. ELEVATION TOP OF HOLE	
74. ELEVATION TOP OF HOLE	
75. ELEVATION TOP OF HOLE	
76. ELEVATION TOP OF HOLE	
77. ELEVATION TOP OF HOLE	
78. ELEVATION TOP OF HOLE	
79. ELEVATION TOP OF HOLE	
80. ELEVATION TOP OF HOLE	
81. ELEVATION TOP OF HOLE	
82. ELEVATION TOP OF HOLE	
83. ELEVATION TOP OF HOLE	
84. ELEVATION TOP OF HOLE	
85. ELEVATION TOP OF HOLE	
86. ELEVATION TOP OF HOLE	
87. ELEVATION TOP OF HOLE	
88. ELEVATION TOP OF HOLE	
89. ELEVATION TOP OF HOLE	
90. ELEVATION TOP OF HOLE	
91. ELEVATION TOP OF HOLE	
92. ELEVATION TOP OF HOLE	
93. ELEVATION TOP OF HOLE	
94. ELEVATION TOP OF HOLE	
95. ELEVATION TOP OF HOLE	
96. ELEVATION TOP OF HOLE	
97. ELEVATION TOP OF HOLE	
98. ELEVATION TOP OF HOLE	
99. ELEVATION TOP OF HOLE	
100. ELEVATION TOP OF HOLE	

NOT FOR CONSTRUCTION



CHICAGO SHORELINE PROTECTION PROJECT
MORGAN SHOAL REVETMENT RECONSTRUCTION
45TH STREET TO 51ST STREET
CHICAGO, IL 60653
CHICAGO PARK DISTRICT
CITY OF CHICAGO, MAYOR LORI E. LIGHTFOOT

Architect of Record:
SMITHGROUP
ADDRESS: 35 EAST WACKER
SUITE 800
CHICAGO, ILLINOIS 60601
PHONE: 312.641.0770
WEB: www.smithgroup.com

Stantec Consulting Services, Inc.
Chicago, IL
Structural Engineers of Record

Infrastructure Engineering, Inc.
Chicago, IL
Civil Engineers of Record

Latent Design Corporation
Chicago, IL
Architects

Wang Engineering, Inc.
Lombard, IL
Geotechnical Consultant

Living Habitats, LLC
Chicago, IL
Ecological Consultant

American Surveying & Engineering
Chicago, IL
Surveying Consultant

CCJM Engineers
Chicago, IL
MEP Consultant

Thornton Tomasetti
Chicago, IL
Structural Consultant

Mark	Description	Date
1	Schematic Design	05/2022
2	60% Detailed Design	01/2023
3	90% Final Engineering	10/2023